


# The jet



This jet is loaded with capsules by air door traps and the capsule containing the gasoline is put into a pressure of say 10,000 lbs p.s.i. the capsule is burst and out comes the gasoline in that high press. of air or something else to take place of air two electrodes set it off the capsule falls between the ends of the electrodes every time the charge leaving by the opening of the electronic valves goes thro the vacuum chamber and hits the air press. chamber the air in chamber is the bullet at just the right split sec. the elect muzzle plug controlled by electronics is opened and the recid when all is timed o.k sends saucers at good speed.