

~~Secret~~

7 April 1949

SUBJECT: Security Inspection

2. Cont'd.

g. Pressure has been exerted to get the Post Engineers to keep the drainage system clear and to take measures to check the erosion. These efforts will be continued but little progress on erosion control can be expected until the rains diminish. Ditches have been filled, dirt moved and replaced, native grasses planted, but the rains return too soon and much of the effort invested is therefore wasted. Plans are prepared for an interim erosion control effort, and a study is being made to estimate the cost of resloping the cuts in order that the rainfall may be drained with less damaging results. Initial estimates run in the neighborhood of twenty thousand dollars (\$20,000.00).

3. With the exception of halting the erosion, all deficiencies listed in the security inspection report have been cleared away. It is therefore requested that the monthly report of action taken required by cited letter be discontinued.

*Richard W. Kline*

RICHARD W KLINE  
Lt Col, USAF  
Commanding

~~Secret~~

Short Title BC-10-0-214