

Tape 46/6

02 18 46 46 CC Jack, are you sto - you all stowing the ALFMED now or are you done?

CMP What's that, Bob?

CC Are you all done with the ALFMED now, Ron?

CMP Yes, I've got to get it to - get the plate moved back down there yet.

CC Okay, Ron - -

CMP ... get the blindfold off first so I can see what I'm doing.

CC Roger. I just want you to know. We've got a real long update coming up to you here on the LOI abort charts and that - and it's going to be, probably, a difficult readup. And you're the most familiar with the charts; you probably would want to take them. But whenever you want to take them, they are on - charts on page 3-81, 3-82, and then the cue card for LOI limits. Whenever you want to take them. It will be a lengthy one.

CMP Stand by, Bob. Let us get squared away from the ALFMED; then we can get going on that.

CC No, I don't want to hurry you, Ron. I just want you to know what - when - just get yourself comfortable and be ready to take them whenever you want them. It's going to be a lengthy time, though.

02 18 47 51 CMP Okay.

CDR Hey, Bob, I'm looking at what - what Jack was talking about; and it's definitely not a particle that's nearby because there is another one I can look at and get a three-dimensional comparison with. It is a - it is a bright object, and it's obviously rotating because it's flashing. It's way out in the distance, as I say, because there are particles that are close by and it's obviously not one of those. It's apparently rotating in a